

**Course 482**  
**Sources and Control of Volatile Organic Air Pollutants**

**AGENDA**

**LOCATION**

On-Line

**MODERATOR**

J.W. Crowder

<b>DAY &amp; TIME</b>	<b>SUBJECT</b>	<b>SPEAKER</b>
-----------------------	----------------	----------------

***Monday, October 5***

8:30	Course Overview	J. Crowder
8:45	Properties and Fundamentals	W. Franek
10:30	BREAK	
10:45	Properties and Fundamentals (cont'd)	J. Crowder
12:30	Source Measurement Techniques	W. Franek
12:45	ADJOURN	

***Tuesday, October 6***

8:30	Source Measurement Techniques (cont'd)	W. Franek
10:00	National Sources and the Regulatory Approach	W. Franek
10:30	BREAK	
10:45	National Sources and the Regulatory Approach (cont'd)	W. Franek
11:15	Surface Coating	J. Crowder
12:45	ADJOURN	

***Wednesday, October 7***

8:30	Surface Coating (cont'd)	J. Crowder
8:45	Graphic Arts	J. Crowder
10:15	Calculating VOC Content of Coatings and Inks	J. Crowder
10:30	BREAK	
10:45	Calculating VOC Content of Coatings and Inks (cont'd)	J. Crowder
12:15	Oil and Gas Production	J. Crowder
12:45	ADJOURN	

***Thursday, October 8***

8:30	Oil and Gas Production (cont'd)	J. Crowder
9:00	Petroleum Refining	W. Franek
10:00	Petroleum Product Storage and Distribution	J. Crowder
10:30	BREAK	
10:45	Petroleum Product Storage and Distribution (cont'd)	J. Crowder
12:00	Degreasing	W. Franek
12:45	ADJOURN	

DAY & TIME	SUBJECT	SPEAKER
------------	---------	---------

**Friday, October 9**

8:30	Degreasing (cont'd)	W. Franek
8:45	Dry Cleaning	W. Franek
9:45	Introduction to Control Technology	J. Crowder
10:30	BREAK	
10:45	Introduction to Control Technology (cont'd)	J. Crowder
12:45	ADJOURN	

---

Jerry W. Crowder, Ph.D., P.E.  
Crowder Environmental Associates, Inc.  
120 Cherry Circle  
Dyersburg, Tennessee 38024  
Tel: 731-286-1554  
Fax: 731-286-4910  
Cell: 731-589-0911  
E-mail: jwcrowder@cableone.net

---

William J. Franek, Ph.D., P.E.  
William Franek, LLC  
6807 West 64<sup>th</sup> Place  
Chicago, IL 60638  
Tel: 312 -919-0341  
E-mail: billfranek@gmail.com